Commonwealth Edison Con Jany Quad 29'es Generating Station 22"10 200th Avenue North Cordova II. 61242/9"40 21" 309-054-2241



LWP-97-101

October 24, 1997

U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Attn:

Document Control Desk

Reference:

Quad Cities Nuclear Power Station

Docket Number 50-265, DPR-30, Unit Two

Enclosed is Licensee Event Report (LER) 97-003, Revision 1, for Quad Cities Nuclear Power Station. This port is submitted in accordance with the requirements of the Code of Federal Regulations, Title 10, Part 50.73(a)(2)(ii)(B). The licensee shall report any event or condition that resulted in the condition of the nuclear power plant, including its principal safet, barriers, being seriously degraded, or that resulted in the nuclear plant being in a condition that was outside the design basis of the plant. This event dealt with 2B Core Spray Rorm Cooler (CSRC) Fouled due to Hydrolyzing Debris.

This report is being submitted to make the following commitment:

Modification DCP 9500057 to install flow indications to the Residual Heat Removal System and CS Room Coolers is planned to be installed on Unit 1 during Q1R15.

IEAA /

9710310193 971024 PDR ADOCK 05000265 S PDR

STMGR\LER\97101

Marie Committee Committee

A Unicom Company

If there are any questions or comments concerning this letter, please refer them to Charles Peterson, Regulatory Affairs Manager at 309-654-2241, ext. 3609.

Respectfully,

COMMONWEALTH EDISON COMPANY QUAD CITIES NUCLEAR POWER STATION

L. W. Pearce

Site Vice President

and Acting Station Manager

LWP/CP/plm

Enclosure

A. B. Beach, Regional Administrator, Region III R. M. Pulsifer, Project Manager, NRR

C. C. Miller, Senior Resident Inspector, Quad Cities W. D. Leech MidAmerican Energy Company D. C. Tarisa. IdAmerican Energy Company

M. E. Wasse L. censing, ComEd

F. A. Spangenberg, Regulatory Affairs Manager, Dresden

INPO Records Center