JUN 28 1989

Docket No. 50-254 Docket No. 50-265

Commonwealth Edison Company ATTN: Mr. Cordell Reed Senior Vice President Post Office Box 767 Chicago, IL 60690

Gentlemen:

This refers to the routine safety inspection conducted by Mr. J. H. Neisler of this office on June 5-9, 1989, of activities at Quad Cities Station, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-29 and No. DPR-30 and to the discussion of our findings with Mr. R. Robey and other members of your staff at the conclusion of the inspection. The purpose of the inspection was to review the implementation of Bulletin 88-10 requirements relative to molded case circuit breakers.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely

ORIGINAL SIGNED BY RICHARD W. COOPER

R. W. Cooper, Chief Engineering Branch

Enclosures: Inspection Reports No. 50-254/89014(DRS); No. 50-265/89014(DRS)

See Attached Distribution

RIII Neisler/sm Advision Gardner Cooper 40 SP07030283 890628 FDR ADOCK 05000254 Commonwealth Edison Company

Distribution

.

cc w/enclosure: T. Kovach, Nuclear Licensing Manager R. L. Bax, Station Manager DCD/DCB (RIDS) Licensing Fee Management Branch Resident Inspector, RIII Richard Hubbard J. W. McCaffrey, Chief, Public Utilities Division