## SEP 20 1989

Docket Nos. 50-413, 50-414 License Nos. NPF-35, NPF-52

Duke Power Company
ATTN: Mr. H. B. Tucker, Vice President
Nuclear Production Department
422 South Church Street
Charlotte, NC 28242

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NCS. 50-413/89-26 AND 50-414/89-26

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by T. R. Collins on August 21-24, 1989. The inspection included a review of activities authorized for your Catawba facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Your attention is invited to the unresolved items identified in the Inspection Report. This matter will be pursued during future inspections.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

Douglas M. Collins, Chief Emergency Preparedness and Radiological Protection Branch

(original signed by W. Rankin)

Division of Radiation Safety and Safeguards

and saleg

Enclosure: NRC Inspection Report

cc w/encl: (See page 2)

8910030276 89J920 PDR ADOCK 05000413 0 PDC %

cc w/encl: T. B. Owen, Station Manager State of South Carolina

bcc w/encl: K. N. Jabbour, NRR NRC Resident Inspector Document Control Desk

RII: DRSS TCollins 8/19/89 RII: DRSS J R. Shortway JPOtter Q8/20/ 89 MShymlock 81./89