

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 36

National Average: 38

2x National Average: 76

National Median: 21.5

Average for Selected Dockets: 36

Facility Name: Peach Bottom 2 Docket (050- 00277)

Details	Department	Work Type	Docket/Report
Communications / IR			
55 - Communication Equipment LTA	D - Emergency Planning	D - Emergency Drill	050-00277/2001-014
55 - Communication Equipment LTA	D - Emergency Planning	D - Emergency Drill	050-00277/2001-014
55 - Communication Equipment LTA	D - Emergency Planning	D - Emergency Drill	050-00277/2001-014
55 - Communication Equipment LTA	D - Emergency Planning	D - Emergency Drill	050-00277/2001-014
Number of Items for this Docket: 4			
Percent of Total for this Docket: 11			
Management and Supervision / IR			
36 - Scheduling and planning LTA	D - Emergency Planning	D - Emergency Drill	050-00277/2001-012
40 - Individual Corrective Action LTA	D - Emergency Planning	D - Emergency Drill	050-00277/2001-011
40 - Individual Corrective Action LTA	O - Operations	A - Administrative	050-00277/2000-013
40 - Individual Corrective Action LTA	O - Operations	A - Administrative	050-00277/2000-013
40 - Individual Corrective Action LTA	O - Operations	Z - Other	050-00277/2001-004
41 - Action not begun or untimely	D - Emergency Planning	D - Emergency Drill	050-00277/2001-004
47 - Root Cause LTA	G - Engineering	Z - Other	050-00277/2001-014
48 - Audits or problem identification LTA	Q - QA/QC	D - Emergency Drill	050-00277/2001-012
Number of Items for this Docket: 8			
Percent of Total for this Docket: 22			
Procedures and Reference Document / IR			
11 - No procedure / reference documents	D - Emergency Planning	D - Emergency Drill	050-00277/2001-011
11 - No procedure / reference documents	G - Engineering	G - Design	050-00277/2001-006
11 - No procedure / reference documents	G - Engineering	Z - Other	050-00277/2000-013
12 - Procedure technical content LTA	D - Emergency Planning	D - Emergency Drill	050-00277/2001-011
12 - Procedure technical content LTA	P - Procedure Writers	P - Procedure Dev	050-00277/2001-005
13 - Procedure has human factors deficiencies	D - Emergency Planning	D - Emergency Drill	050-00277/2001-011
13 - Procedure has human factors deficiencies	P - Procedure Writers	P - Procedure Dev	050-00277/2001-014
Number of Items for this Docket: 7			
Percent of Total for this Docket: 19			
Training / IR			
02 - Training LTA	T - Training	D - Emergency Drill	050-00277/2001-012
04 - Task Qualification	O - Operations	O - Control Room Ops	050-00277/2000-013
Number of Items for this Docket: 2			
Percent of Total for this Docket: 6			

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 36

National Average: 38

2x National Average: 76

National Median: 21.5

Average for Selected Dockets: 36

Facility Name: Peach Bottom 2 Docket (050- 00277)

Details	Department	Work Type	Docket/Report
Work Factors / IR			
81 - Work Package Quality LTA	G - Engineering	F - Modification	050-00277/2001-014
84 - Non-conserv. decision / Questioning LTA	D - Emergency Planning	D - Emergency Drill	050-00277/2001-014
84 - Non-conserv. decision / Questioning LTA	D - Emergency Planning	M - Maint / Repair	050-00277/2001-004
84 - Non-conserv. decision / Questioning LTA	G - Engineering	F - Modification	050-00277/2001-014
84 - Non-conserv. decision / Questioning LTA	G - Engineering	V - Troubleshooting	050-00277/2001-004
84 - Non-conserv. decision / Questioning LTA	O - Operations	V - Troubleshooting	050-00277/2001-004
85 - Team interactions LTA	D - Emergency Planning	Z - Other	050-00277/2000-013
85 - Team interactions LTA	T - Training	Z - Other	050-00277/2000-013
93 - Awareness or attention LTA	G - Engineering	A - Administrative	050-00277/2000-013
Number of Items for this Docket: 9			
Percent of Total for this Docket: 25			
Procedures and Reference Document / LER			
12 - Procedure technical content LTA	M - Mechanical	M - Maint / Repair	050-00277/2001-004-00
12 - Procedure technical content LTA	O - Operations	B - Bal of Plant Ops	050-00277/2001-005-00
12 - Procedure technical content LTA	O - Operations	O - Control Room Ops	050-00277/2001-001-00
12 - Procedure technical content LTA	P - Procedure Writers	P - Procedure Dev	050-00277/2001-003-00
Number of Items for this Docket: 4			
Percent of Total for this Docket: 11			
Work Factors / LER			
83 - Work practice or craft skill LTA	M - Mechanical	M - Maint / Repair	050-00277/2001-004-00
92 - Self check LTA	O - Operations	B - Bal of Plant Ops	050-00277/2001-005-00
Number of Items for this Docket: 2			
Percent of Total for this Docket: 6			
Total Items for this Docket: 36			
