

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 44

National Average: 46

2x National Average: 92

National Median: 23

Average for Selected Dockets: 44

Facility Name: Peach Bottom 2 Docket (050- 00277)

Details	Department	Work Type	Docket/Report
Communication / IR			
160 - No communication / information not communicated	M - Mechanical	M - Maintenance / Repair	050-00277/2009-003
Number of Items for this Docket: 1			
Percent of Total for this Docket: 2			
<hr/>			
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00277/2009-003
170 - HSI or information availability / quality LTA	M - Mechanical	T - Testing	050-00277/2009-008
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00277/2009-003
Number of Items for this Docket: 3			
Percent of Total for this Docket: 7			
<hr/>			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	M - Mechanical	T - Testing	050-00277/2009-008
111 - Procedure / reference document technical content	P - Procedure Writers	P - Procedure Dev	050-00277/2008-005
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00277/2009-004
111 - Procedure / reference document technical content	P - Procedure Writers	P - Procedure Dev	050-00277/2008-005
113 - Procedure / reference document development and maintenance L	M - Mechanical	M - Maintenance / Repair	050-00277/2009-003
Number of Items for this Docket: 5			
Percent of Total for this Docket: 11			
<hr/>			
Problem Identification & Resolution / IR			
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00277/2009-003
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00277/2009-008
142 - Operating experience (OE) review LTA	M - Mechanical	T - Testing	050-00277/2009-008
143 - Tracking / trending LTA	O - Operations	O - Control Room Ops	050-00277/2009-003
143 - Tracking / trending LTA	M - Mechanical	M - Maintenance / Repair	050-00277/2009-003
146 - Evaluation LTA	S - Specialized task force	W - Assessment	050-00277/2009-008
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00277/2009-003
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00277/2009-008
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00277/2009-003
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00277/2009-003
Number of Items for this Docket: 10			
Percent of Total for this Docket: 23			
<hr/>			
Work Planning & Practices / IR			
183 - Pre-job activities LTA	O - Operations	O - Control Room Ops	050-00277/2008-005

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 44

National Average: 46

2x National Average: 92

National Median: 23

Average for Selected Dockets: 44

Facility Name: Peach Bottom 2 Docket (050- 00277)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
183 - Pre-job activities LTA	O - Operations	O - Control Room Ops	050-00277/2008-005
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00277/2008-005
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00277/2009-004
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00277/2008-005
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00277/2009-008
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00277/2009-003
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00277/2009-003
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00277/2009-003
185 - Procedural adherence LTA	F - Fuel Handling	R - Refueling	050-00277/2009-003
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00277/2009-003
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00277/2009-003
186 - Failure to take action / meet requirements	M - Mechanical	T - Testing	050-00277/2009-008
190 - Failure to stop work / non-conservative decision making	M - Mechanical	M - Maintenance / Repair	050-00277/2009-003
190 - Failure to stop work / non-conservative decision making	M - Mechanical	M - Maintenance / Repair	050-00277/2009-003
191 - Team interactions LTA	O - Operations	O - Control Room Ops	050-00277/2008-005
191 - Team interactions LTA	O - Operations	O - Control Room Ops	050-00277/2008-005
197 - Self-check LTA	O - Operations	O - Control Room Ops	050-00277/2009-004
Number of Items for this Docket: 18			
Percent of Total for this Docket: 41			

Oversight / LER

130 - Inadequate supervision / command and control	W - Work Control / Scheduling Outage Pla	B - Bal of Plant Ops	050-00277/2009-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 2			

Procedures & Reference Document / LER

111 - Procedure / reference document technical content	O - Operations	B - Bal of Plant Ops	050-00277/2009-002-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 2			

Work Planning & Practices / LER

183 - Pre-job activities LTA	O - Operations	B - Bal of Plant Ops	050-00277/2009-001-00
185 - Procedural adherence LTA	O - Operations	B - Bal of Plant Ops	050-00277/2009-001-00
186 - Failure to take action / meet requirements	O - Operations	B - Bal of Plant Ops	050-00277/2009-001-00
187 - Action implementation LTA	O - Operations	B - Bal of Plant Ops	050-00277/2009-002-00

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 44
National Average: 46
2x National Average: 92
National Median: 23
Average for Selected Dockets: 44

Facility Name: Peach Bottom 2 Docket (050- 00277)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / LER			
196 - Independent verification / plant tours LTA	O - Operations	B - Bal of Plant Ops	050-00277/2009-001-00
Number of Items for this Docket: 5			
Percent of Total for this Docket: 11			

Total Items for this Docket: 44
