

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 19

National Average: 30

2x National Average: 60

National Median: 18

Average for Selected Dockets: 19

Facility Name: McGuire 1 Docket (050- 00369)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00369/2010-002
171 - Simulator fidelity LTA	D - Emergency Planning	D - Emergency Drill	050-00369/2009-501
Number of Items for this Docket: 2			
Percent of Total for this Docket: 11			
Oversight / IR			
130 - Inadequate suprevison / command and control	D - Emergency Planning	D - Emergency Drill	050-00369/2009-501
131 - Management expectations or directions LTA	O - Operations	B - Bal of Plant Ops	050-00369/2010-002
131 - Management expectations or directions LTA	D - Emergency Planning	D - Emergency Drill	050-00369/2009-501
Number of Items for this Docket: 3			
Percent of Total for this Docket: 16			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00369/2010-002
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00369/2010-002
113 - Procedure / reference document development and maintenance L	D - Emergency Planning	D - Emergency Drill	050-00369/2009-501
Number of Items for this Docket: 3			
Percent of Total for this Docket: 16			
Problem Identification & Resolution / IR			
143 - Tracking / trending LTA	O - Operations	B - Bal of Plant Ops	050-00369/2010-002
150 - Programmatic deficiency	D - Emergency Planning	D - Emergency Drill	050-00369/2009-501
Number of Items for this Docket: 2			
Percent of Total for this Docket: 11			
Training / IR			
100 - Training LTA	O - Operations	B - Bal of Plant Ops	050-00369/2010-002
Number of Items for this Docket: 1			
Percent of Total for this Docket: 5			
Work Planning & Practices / IR			
186 - Failure to take action / meet requirements	D - Emergency Planning	D - Emergency Drill	050-00369/2009-501
187 - Action implementation LTA	G - Engineering	G - Design	050-00369/2010-002
189 - Recognition of adverse condition / questioning attitude LTA	D - Emergency Planning	D - Emergency Drill	050-00369/2009-501
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	B - Bal of Plant Ops	050-00369/2010-002
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00369/2010-002
192 - Work untimely	M - Mechanical	M - Maintenance / Repair	050-00369/2010-002

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 19
National Average: 30
2x National Average: 60
National Median: 18
Average for Selected Dockets: 19

Facility Name: McGuire 1 Docket (050- 00369)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
192 - Work untimely	M - Mechanical	M - Maintenance / Repair	050-00369/2010-002
Number of Items for this Docket: 7			
Percent of Total for this Docket: 37			
<hr/>			
Work Planning & Practices / LER			
189 - Recognition of adverse condition / questioning attitude LTA	G - Engineering	F - Modification	050-00369/2010-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 5			
<hr/>			
Total Items for this Docket: 19			
