

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 12

National Average: 30

2x National Average: 60

National Median: 18

Average for Selected Dockets: 12

Facility Name: Susquehanna 2 Docket (050- 00388)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
171 - Simulator fidelity LTA	O - Operations	O - Control Room Ops	050-00388/2009-005
171 - Simulator fidelity LTA	T - Training	N - Training	050-00388/2009-005
172 - Simulator use LTA	O - Operations	O - Control Room Ops	050-00388/2009-005
172 - Simulator use LTA	T - Training	N - Training	050-00388/2009-005
Number of Items for this Docket: 4			
Percent of Total for this Docket: 33			

Training / IR			
101 - Training process problem	O - Operations	O - Control Room Ops	050-00388/2009-005
101 - Training process problem	T - Training	N - Training	050-00388/2009-005
103 - Simulator training LTA	O - Operations	O - Control Room Ops	050-00388/2009-005
103 - Simulator training LTA	T - Training	N - Training	050-00388/2009-005
Number of Items for this Docket: 4			
Percent of Total for this Docket: 33			

Work Planning & Practices / IR			
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00388/2009-005
186 - Failure to take action / meet requirements	D - Emergency Planning	O - Control Room Ops	050-00388/2009-005
193 - Non-conservative action	Z - Other / Unknown	Z - Other / Unknown	050-00388/2010-002
197 - Self-check LTA	D - Emergency Planning	Q - Fire Protection	050-00388/2009-005
Number of Items for this Docket: 4			
Percent of Total for this Docket: 33			

Total Items for this Docket: 12
