

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION I 475 ALLENDALE ROAD KING OF PRUSSIA, PA 19408-1415

February 23, 2000

Docket No. 030-20934 License No. 37-23341-01

Michael Claflin Superintendent Wastewater Treatment Facility Borough of Royersford 300 Main Street P. O. Box 188 Royersford, PA 19468

SUBJECT: Fourth Quarter 1999 TLD Monitoring Results

Dear Mr. Claflin:

Enclosed are the results of the TLD Monitoring performed by the NRC at the Royersford Wastewater Treatment Facility for the period October 15, 1999 through January 3, 2000 (fourth quarter 1999). If you have any questions, please contact Betsy Ullrich of my staff at (610) 337-5040.

Thank you for your cooperation.

Sincerely,

Original signed by John D. Kinneman

John D. Kinneman, Chief Nuclear Materials Safety Branch 2 Division of Nuclear Materials Safety

Enclosure:

Fourth Quarter 1999 TLD Monitoring Results

CC:

Daniel R. Neeley, UniTech Services Group, Radiation Safety Officer Michael Fuller, UniTech Services Group, Manager, Health Physics and Engineering David Allard, Director, PADEP/BRP Ivna Shanbaky, PADEP M. Claflin 2 Wastewater Treatment Facility

Distribution: PUBLIC Nuclear Safety Information Center (NSIC) Region I Docket Room R. Bores, RI

DOCUMENT NAME: C:\\37-23341-01.03212000.wpd

To receive a copy of this document, indicate in the box: "C" = Copy w/o attach/encl "E" = Copy w/ attach/encl "N" = No copy

OFFICE	DNMS/RI	Ν	DNMS/RI	DNMS/RI		
NAME	Eullrich EXU		Jkinneman JDK			
DATE	02/15/00		02/15/00			

Enclosure 1: Landauer TLD Results

Period: October 15, 1999 thorugh January 3, 2000

Deploy dosimeter

Transit dosimeter

XX.

XX.

Location Gross Exposure, Standard Calendar Quarter (millirem) Reed Bed #1, Cell A 1. 665.8 Reed Bed #2, Cell B 704.9 2. 3. Fence by Reed Bed #1 (east) 35.6 Settling tanks rail - by Reed Bed #1 4. 108.4 Settling tanks rail - by Secondary Digester 5. 42.6 Rear Fence (north) 6. 24.1 Fence by Reed Bed #2 (west) 7. 22.6 8. Light Switch of Storage Building 21.6 Secondary Digester - center of west side 9. 24.1 10. 2nd Story rail by Office back door 22.6 11. Front fence (south) 22.4 Support rail of stairway to Office back door 12. 23.7 13. Primary Digester - top of ladder 64.4 Secondary Digester - center of east side 14. 89.8 Settling tanks rail - path to Laboratory Building 15. 23.4 16. Laboratory (previous office) 27.2

16.8

17.2