

From: James Noggle
To: Larry Rosenmann
Date: 03/05/2007 1:52:16 PM
Subject: Re: IPEC Tracer Indications

Thanks, Larry. I will do my best.

Regards,

Jim

>>> "Larry Rosenmann" <larosenm@gw.dec.state.ny.us> 03/01/2007 1:13 PM >>>

Jim - I would like to encourage you to have Entergy put together the cross sections that Tom has been so strongly requesting. They would have been very helpful to me when I sought to understand the information we have already received from the tracer test. I am sure they will be even more useful if they can be available at the proposed meeting in a few weeks.

Larry A. Rosenmann
NYSDEC Division of Solid & Hazardous Materials
625 Broadway, Albany, NY 12233-7258
Phone: (518) 402-8594 Fax: (518) 402-9024
larosenm@gw.dec.state.ny.us

"Great ideas are nearly always profoundly complex
and subject to misreading" Suzanne Fields

>>> "James Noggle" <JDN@nrc.gov> 3/1/2007 8:37 AM >>>

We are now 3 weeks into the Unit 2 tracer test and 1 week behind in Ozark Lab results. Currently tracer has been detected in MW-30, 31, and 32 as reported last week. This week, manhole 5 and MW-53 have also detected tracer. As you remember, MH-5 sees the discharge from the Unit 2 containment footer drain system, which would also be expected to collect Unit 2 SFP leakage. MW-53 is a Unit 1 plume well, which also showed drawdown from the pump test.

GZA suggests having a telephone discussion in about 2 more weeks, so they have some data trends and direction established for discussion. If you are agreeable, let's aim for Wednesday, March 14th. Let me know of your availability.

With respect to ground water sampling performance indicators, GZA has not identified another indicator other than radionuclide analysis. They are still looking at temperature, but due to plant high water quality, other water sampling parameters have not shown much promise.

Regards,

Jim

54
B/54