

101 Greenwood Ave., Suite 150
Jenkintown, PA 19046
Phone: 215-663-5910
Fax: 215-663-2451



p-7

37-30766-01

03036104

To: Tom Thompson	From: Julie Cassidy
Fax: 610-337-5269	Date: 8/24/07
Phone:	Pages:
Re Pa Diagnostic Imaging	CC:

Urgent For Review Please Comment Please Reply Please Recycle

Tom,

The unit used to survey Pa Diagnostic Imaging , was calibrated by Capintec on 2/7/06. and surveyed by
The calibration unit at Mainline Diagnostic Imaging at Great Valley ,22 Morehall Road ,Malvern Pa

Julie Cassidy

140933



CRC®-15W
Certificate of Detector Calibration
FORM # 5133-5116 Rev. E

Test Engineer: Anthony Di... Q.C. Acceptance: Rickson GJ

Final Calibration Date: 2 / 7 / 06

CRC-15W S/N: 170778 Detector S/N: 30022-01749-E

Preliminary BKG Counts: 501 cpm (300 - 900 cpm)

Auto Calibration Results - Gain Reference: 1769

Calibration Factor = 1.106 (0.884 - 1.107)

Conversion Factor = 10.98 (10.34 - 11.65)

Test Results:

Activity Deviation % (0.0% ±5.0%)	0.3
Energy Deviation % (0.0% ±2.5%)	0.6

Factory Setup Data Entered OK

Final Background Reading: 5.00 cpm (300 - 900cpm)