



**SAFETY INSPECTION REPORT  
AND COMPLIANCE INSPECTION**

1. LICENSEE STS Acquisition Company REPORT NUMBER(S) 2008-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-14020	4. LICENSE NUMBER(S) 48-18672-01	5. DATE(S) OF INSPECTION 5/21 and 22/08	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 3.1 – 3.7		

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S) 3121	2. PRIORITY 5	3. LICENSEE CONTACT Mark Manske – RSO	4. TELEPHONE NUMBER 414-577-1329
----------------------------	------------------	------------------------------------------	-------------------------------------

<input checked="" type="checkbox"/>	Main Office Inspection	Next Inspection Date: 5/2013
<input checked="" type="checkbox"/>	Field Office Grand Rapids, Michigan	
<input type="checkbox"/>	Temporary Job Site Inspection	

**PROGRAM SCOPE**

The licensee was authorized to use and store licensed material at five permanent field stations and temporary job sites within NRC jurisdiction. At the time of the inspection, the licensee only had licensed material at the Grand Rapids and Marquette, Michigan field stations. The licensee had 15 gauges out of the Grand Rapids site and eight gauges out of the Marquette site. The licensee employs approximately 25 individuals throughout the company.

**Performance Observations**

The inspector interviewed the RSO and several gauge operators and found that the licensee staff had adequate knowledge to ensure safe use of the gauge. The inspector reviewed the licensee's leak test records, inventory, transportation documentation and dosimetry records; no abnormal issues were identified. No licensed operations were on-going within NRC jurisdiction at the time of the inspection. The licensee demonstrated the proper methods to transport and store the gauge when not in use.