John Richmond

From:

stevie.dupont@exeloncorp.com

Sent:

Monday, November 10, 2008 7:50 AM

To:

John Richmond

Cc:

jhansi.kandasamy@exeloncorp.com; Calvin.Taylor@exeloncorp.com

Subject:

Current Open Status Report

Attachments:

Open Status 11-10.pdf

John, attached is the current status report...at a time that would work best for you, I would like to call you and go over each item and to ensure that you have or will have what you need for the exit today.

Stevie Du Pont RA - TeamOysterCreek 609-971-4033 <<Open Status 11-10.pdf>>

Received: from TWMS01.nrc.gov (148.184.200.145) by R1MS01.nrc.gov (148.184.99.10) with Microsoft SMTP Server (TLS) id 8.1.291.1; Mon, 10 Nov 2008 07:49:56 -0500

Received: from mail2.nrc.gov (148.184.176.43) by TWMS01.nrc.gov

(148.184.200.145) with Microsoft SMTP Server id 8.1.291.1; Mon, 10 Nov 2008

07:49:56 -0500 X-Ironport-ID: mail2 X-SBRS: 3.3

X-SBRS: 3.3 X-MID: 23207482

X-IronPort-Anti-Spam-Filtered: true

X-IronPort-Anti-Spam-Result:

AtYAAlu8F0nGHb8zhWdsb2JhbACCSTAjj3mBDwEBAQoLChgEP6sbCYoLglt9

X-IronPort-AV: E=Sophos;i="4.33,575,1220241600";

d="pdf"?scan'208,217";a="23207482"

Received: from webmail.exeloncorp.com (HELO exeloncorp.com) ([198.29.191.51])

by mail2.nrc.gov with ESMTP; 10 Nov 2008 07:49:56 -0500

Received: from ([130.197.106.102]) by cccuniron1.exeloncorp.com with ESMTP id

5402003.114827310; Mon, 10 Nov 2008 06:49:36 -0600

Received: from CCCMSXCH02.energy.power.corp ([130.197.153.201]) by

CCCMSCON02.energy.power.corp with Microsoft SMTPSVC(6.0.3790.3959); Mon, 10

Nov 2008 06:49:36 -0600

X-MimeOLE: Produced By Microsoft Exchange V6.5

Content-Class: urn:content-classes:message

MIME-Version: 1.0

Subject: Current Open Status Report Date: Mon, 10 Nov 2008 06:49:36 -0600

Message-ID:

<53EC8803AC832C4198D6C456E8C3300C020D099A@CCCMSXCH02.energy.power.corp>

X-MS-Has-Attach: yes X-MS-TNEF-Correlator:

Thread-Topic: Current Open Status Report

Thread-Index: AcIDMskTtxJSHq0fQw69doTcqitE3A==

From: <stevie.dupont@exeloncorp.com>

To: <john.richmond@nrc.gov>

CC: <jhansi.kandasamy@exeloncorp.com>,

<Calvin.Taylor@exeloncorp.com>

Return-Path: stevie.dupont@exeloncorp.com

X-OriginalArrivalTime: 10 Nov 2008 12:49:36.0869 (UTC) FILETIME=[C9BB4950:01C94332]

Content-Type: multipart/mixed;

boundary="--- = NextPart 001 01C94332.C95DB853"

OYCK - Quarterly Integrated Inspection NRC Requests Report Post-Approval Site Inspection for License Renewal

Assigned To: All Requested By: All Status: Open

Date: 11/10/08 6:41am

Request Number 000071331

Description

Intake structure inspections on evening of 10/28 and morning of 10/29

Comments

UPDATE on 11/8 - \"eyes on\" that evaluation of the inspections was ongoing. Expect

delivery to be posted on 11/9

Actions Taken

Assigned To

Chuck Albert

Requested By

John Richmond

Status

Open

Request Number 000071341

Description

final Drywell NDE Reports - Required for Exit: provide final VT and volumetric (UT) testing results to John Richmond, for drywell related inspections, both those performed inside the

drywell and those performed from the outside (sand bed region)

Comments

Want as soon as available 11/06/08 UPDATE: still need UT data for 19 locations, has 11A,

13A and 17D and Trench 17. Still needs UT data for Trench 5 (6\" lower in grout)

Actions Taken

provided - UT data for Trench 5 (6\" lower in grout) provioded - 11A, 13A and 17D and

Trench 17

Assigned To

Pete Tamburro

Requested By

John Richmond

Status

Open

Request Number 000071351

Description

Curb caulking. Ensure caulking is inspected prior to removal for NDE. Update 11/6/08 Moisture barrier shell and curb has preliminary data for results but not final data (Visual).

NRC needs Final Data.

Sam Markos - the mositure seal was inspected as part of the drywell monitoring

Comments

inspection on 11/6. This needs to be included in the CREM for the inspection. UPDATE on 11/8 - the is expected to be complete on 11/8. The inspection (Visual) On Engineering

Priority Board to be completed prior to morning of 11/10

Actions Taken

Assigned To

Tom Roddey

Requested By

John Richmond

Status

Open

Request Number 000071361

Description

Provide Drywell Structural Inspection Report.

NRC requested a copy of the Drywell Structual Inspection Report (Report 153-011)

Comments

including color pictures. The pictures can be posted to the Engineer Folder of the K drive. Note - if teh full report will not be completed in teh next few days, provide pictures and

full summary from PIMS CREM

Actions Taken

In- progress high level summary opf the inspection results were provided. When

completed the summary will be posted in PIMS CREM by engineering. Discussed with Sam

Markos and expect to be in CREM by Monday - efforts are being taken to complete

reviews by nights (11/8)

Assigned To

Tom Roddey

Requested By

John Richmond

Status

Open

Request Number 000071371

Description

A.1.27 Item (27) for moisture barrier seal inspection.

Committed to ASME IWE inspection but commitment states \"during PEO\" - need to

Comments

resolve this or if inspection met ASME IWE requirements. Per Tamburro - we will satisfy the committment and inspect per ASME IWE or use the committment process to revise

the committment.

Actions Taken

Assigned To

Pete Tamburro

Requested By

John Richmond

Status

Open

Request Number 000071381

Description

Requested data prior to Exit Status

Required for Exit: The following three items are beining tracked by RA for the LR Inspection Exit: 1. the UT results from trenches located in Bay 5 and 17. The NDE is complete and turned over to Engineering on 11/5. The NRC will complete a parallel review

Comments

with engineering. 2.The VT inspection have all been completed and paperwork reviewed by NRC. - This item is complete. 3. The 19 DW locations - UT is in progress with 5 locations complete. Interference with Bay 13 - to be removed and UT to complete on

11/5/08. The NRC will review in parallel.

Actions Taken

Item 1 - UTs except the last 6 inch of trench was provided; the last 6 inch is POSTED.

Item 2 provided and complete. Item 3 provided and complet.

Assigned To

Pete Tamburro

Requested By

John Richmond

Status

Open

Request Number 000071391

Description

Question on submerged structure inspection scope. Required for Exit: NRC need

clarification on scope of wihich underwater inspections were required.

Comments

Need input from Sam Markos and Mike Hand Per Sam Markos - the scope is in the

procedure ER-OC-450.

Actions Taken

Procedure ER-OC-450 is posted

Assigned To

Tom Roddey

Requested By

John Richmond

Status

Open

Request Number 000071431

Description

Provide completed Tech Evals for startup operability

Comments

Posted Tech Eval for Sand Bed Region on 11/8 Tech Eval 330592)

Actions Taken

1.Posted Tech Eval for Sand Bed Region on 11/8 2.UT Grid (19 Locations) Posted_

3. Trenches Posted on 11/10 4. Transiention Posted_____

Assigned To

Pete Tamburro

Requested By

John Richmond

Status

Open

Request Number 000071451

Description

Confirmation of location for Bay 11 UT on other side

Comments

Please provide documentation confirming correct location for UT readings.

Actions Taken

Posted UT confirmation of Bay 11

Assigned To Requested By Tom Roddey
John Richmond

Status

Open

Request Number 000071461

Description

Revision of Coating inspection procedure and standard used in 2006

Comments

Provide copy of IS-328227-004 and ER-AA-335-018 used in 2006 inspection.

Actions Taken

Assigned To

Calvin Taylor

Requested By

John Richmond

Status

Open

Request Number 000071481

Description

Provide selected IR copies.

Comments

See Cal Taylor for numbers.

Actions Taken

posted

Assigned To

Calvin Taylor

Requested By

John Richmond

Status

Open

Request Number 000071711

Description

Volume 3 of IR

Comments

Actions Taken

Posted Volume 3 of IRs

Assigned To

Stevie Dupont

Requested By

Status

Open

Request Number 000071721

Description

Grid 19A was rescanded.

Comments

Requested a copy of the previous data taken prior to the final - rescanded

Actions Taken

copy provided

Assigned To

Pete Tamburro

Requested By

John Richmond

OYCK - Quarterly Integrated Inspection - Post-Approval Site Inspection for License Ren... Page 4 of 4

Status

Open

Total Number of NRC Requests found: 13