



IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>11</u>




18 1:42 PM

IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>12</u>



18 1:46 PM


IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>13</u>




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture 14



IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>15</u>




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>16</u>



IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>17</u>




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>18</u>




↖ CABLE


IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0 Picture <u>19</u>
--	--



IP3 ASME Section XI, IWL	No: IP3-RPT-STR-03517, Rev: 0
Concrete Containment Inspection	Picture <u>20</u>




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>21</u>




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>22</u>




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>23</u>




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>24</u>



IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>25</u>



IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>26</u>




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>27</u>



IP3
ASME Section XI, IWL
Concrete Containment Inspection

No: IP3-RPT-STR-03517, Rev: 0


Picture 28




IP3
ASME Section XI, IWL
Concrete Containment Inspection

No: IP3-RPT-STR-03517, Rev: 0


Picture 29



IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>30</u>




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>3i</u>



LOOKING UP FROM
ELECT. TUNNEL ROOF

IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>32</u>



18 2:20 PM

BEFORE WOOD REMOVED


IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>33</u>




26 9:03AM

AFTER WOOD REMOVED
~ 3/4" W x 3" W x 3" DEEP

IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture 34



IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>35</u>



IP3
ASME Section XI, IWL
Concrete Containment Inspection

No: IP3-RPT-STR-03517, Rev: 0


Picture 36



IP3
ASME Section XI, IWL
Concrete Containment Inspection

No: IP3-RPT-STR-03517, Rev: 0

Picture 37




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>38</u>



IP3
ASME Section XI, IWL
Concrete Containment Inspection

No: IP3-RPT-STR-03517, Rev: 0

Picture 39



IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>40</u>