




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>41</u>




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>42</u>




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>43</u>




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>44</u>



IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture 45




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>46</u>




18 10:11 AM


IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture 47




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>48</u>



IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>491</u>




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>50</u>



IP3
ASME Section XI, IWL
Concrete Containment Inspection

No: IP3-RPT-STR-03517, Rev: 0


Picture 51



IP3
ASME Section XI, IWL
Concrete Containment Inspection

No: IP3-RPT-STR-03517, Rev: 0


Picture 52



IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>53</u>




<p>IP3 ASME Section XI, IWL Concrete Containment Inspection</p>	<p>No: IP3-RPT-STR-03517, Rev: 0</p>
	<p>Picture <u>54</u></p>



IP3
ASME Section XI, IWL
Concrete Containment Inspection

No: IP3-RPT-STR-03517, Rev: 0


Picture 55



IP3
ASME Section XI, IWL
Concrete Containment Inspection


No: IP3-RPT-STR-03517, Rev: 0

Picture 56



SOME VISIBLE RUST STAINING FROM AFW BUILDING FANS BELOW.

IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0 Picture <u>57</u>
--	--




○ see closeup next pages


IP3
ASME Section XI, IWL
Concrete Containment Inspection

No: IP3-RPT-STR-03517, Rev: 0


Picture 58




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>59</u>




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>60</u>



IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>61</u>




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>62</u>



IP3
ASME Section XI, IWL
Concrete Containment Inspection

No: IP3-RPT-STR-03517, Rev: 0


Picture 63




IP3
ASME Section XI, IWL
Concrete Containment Inspection

No: IP3-RPT-STR-03517, Rev: 0

Picture 64




IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>65</u>



IP3
ASME Section XI, IWL
Concrete Containment Inspection

No: IP3-RPT-STR-03517, Rev: 0

Picture 66



IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>67</u>



IP3 ASME Section XI, IWL Concrete Containment Inspection	No: IP3-RPT-STR-03517, Rev: 0
	Picture <u>68</u>