



Figure 2.3-26— Average Annual Precipitation in the North Branch of the Susquehanna River Basin in Pennsylvania, 1941 - 1970



Reference: Taylor, 1984

Figure 2.3-27— Percent Frequency Distribution of Annual Precipitation in the Southern Part of the North Branch Susquehanna River Basin, 1931 - 1980




Reference: Taylor, 1984

Figure 2.3-28— Locations of Drainage Basins Where Long-Term Water Budget Analyses Have Been Performed




Reference: Taylor, 1984

Figure 2.3-29— Hydrographs of Two USGS Monitoring Wells in Luzerne County Screened in Glacial Outwash



Reference: (USGS, 2008j) (USGS, 2008q)

Figure 2.3-30— Hydrographs of Two USGS Monitoring Wells in Luzerne County Screened in the Catskill Formation



Reference: (USGS, 2008r) (USGS, 2008s)

Figure 2.3-31 — Locations of Groundwater Monitoring Wells




Figure 2.3-32— Locations of BBNPP Surface Water Monitoring Stations




Figure 2.3-33— Locations of Hydrogeological Cross Sections




Figure 2.3-34—Hydrogeological Cross Section A-A'







Figure 2.3-35— Hydrogeological Cross Section B-B'



LEGEND:



073891B22(M)