

## Envirofacts

[Contact Us](#) [Share](#)

You are here: [EPA Home](#) » [Envirofacts](#) » [ICIS](#) » Search Results

# Search Results

- [Home](#)
- [Multisystem Search](#)
- [Topic Searches](#)
- [System Data Searches](#)
- [About the Data](#)
- [Data Downloads](#)
- [Widgets](#)
- [Services](#)
- [Mobile](#)
- [Other Datasets](#)

### ICIS



ICIS Detailed Reports

[<< Return](#)


This page was created on FEB-07-2014

Results are based on data extracted on JAN-23-2014

Note: You are viewing results from the modernized data system, Integrated Compliance Information System (ICIS). The state reporting this data to EPA previously reported the data to a historic data system, Permit Compliance System (PCS). Use the following button to view the historic data from PCS.

#### PCS-ICIS Links

- [Overview](#)
- [Search](#)
  - [Search User Guide](#)
- [Customized Search](#)
  - [Customized Search User Guide](#)
- [Operator Definition](#)
- [PCS Model](#)
- [ICIS Model](#)
- [Law](#)
- [Contact Us](#)
- [Office of Wastewater Management Home](#)



## Facility

FACILITY NAME (1)	GODFREY LAND MINE	NPDES	FLR10R783
STREET 1	9980 138TH SOUTH	SIC CODE	
CITY		MAJOR / MINOR	
COUNTY NAME	Indian River	TYPE OF OWNERSHIP	Privately Owned Facility
STATE	FL	ACTIVITY STATUS	Effective
ZIP CODE	32948	INACTIVE DATE	
REGION	Region 4	TYPE OF PERMIT ISSUED	General Permit Covered Facility
LATITUDE	27.776944	ORIGINAL PERMIT ISSUE DATE	12-SEP-2009
LONGITUDE	-80.6075	PERMIT ISSUED DATE	12-SEP-2009
LAT/LON CODE OF ACCURACY	30	PERMIT EXPIRED DATE	11-SEP-2014
LAT/LON METHOD			
LAT/LON SCALE		USGS HYDRO BASIN CODE	
LAT/LON DATUM		FLOW	
RECEIVING WATERS		FEDERAL GRANT IND	N
PRETREATMENT CODE		SLUDGE CLASS FAC IND	NON-POTW
MAILING NAME		SLUDGE RELATED PERMIT NUM	
MAILING STREET (1)		ANNUAL DRY SLUDGE PROD	
MAILING STREET (2)			
MAILING CITY			
MAILING STATE			
MAILING ZIP CODE			
COGNIZANT OFFICIAL	KEN GODFREY	COGNIZANT OFFICIAL TEL	7725710537

### Activity

FACILITY NAME (1)	GODFREY LAND MINE	NPDES	FLR10R783
-------------------	-------------------	-------	-----------

ACTIVITY NAME	ACTIVITY TYPE DESCRIPTION	ACTIVITY STATUS DESCRIPTION	ACTIVITY STATUS DATE	ACTUAL BEGIN DATE	ACTUAL END DATE
NPDES Permit (CWA)	Permit				

### Contacts

FACILITY NAME (1)	GODFREY LAND MINE	NPDES	FLR10R783
-------------------	-------------------	-------	-----------

No Contacts Found.

### Permit Tracking

FACILITY NAME (1)	GODFREY LAND MINE	NPDES	FLR10R783
PERMIT ISSUED BY		ORIGINAL DATE OF ISSUE	12-SEP-2009
PERMIT ISSUED DATE	12-SEP-2009	PERMIT EXPIRED DATE	11-SEP-2014
EFFECTIVE DATE	12-SEP-2009	RETIREMENT DATE	

Permit Tracking Events:

EVENT DESCRIPTION	EVENT DATE
Permit Expiration	11-SEP-2014
Permit Issued	12-SEP-2009
Permit Effective	12-SEP-2009

### Inspections

FACILITY NAME (1)	GODFREY LAND MINE	NPDES	FLR10R783
-------------------	-------------------	-------	-----------

No Inspections Found.

### Outfalls/Pipe Schedules

FACILITY NAME (1)	GODFREY LAND MINE	NPDES	FLR10R783
OUTFALL TYPE		PIPE NUMBER	
ACTIVITY STATUS		REPORT DESIGNATOR	
LATITUDE		LONGITUDE	
LAT/LON ACCURACY		LAT/LON METHOD	
LAT/LON SCALE		LAT/LON DATUM	
INACTIVE DATE		USGS HYDRO BASIN CODE	
INIT DMR DUE DATE		SUBMISSION UNITS	
PIPE DESCRIPTION		UNITS IN SUBM. PERIOD	
INIT REPORTING DATE		REPORTING UNITS	
UNITS IN REPORTING PERIOD		DMR COMMENT	

## Limits Report

FACILITY NAME (1)	GODFREY LAND MINE	NPDES	FLR10R783
PIPE NUMBER			
PIPE DESCRIPTION		REPORT DESIGNATOR	
DMR COMMENT		LIMIT SET TYPE	

No ICIS Limits Report Found.

## Measurements and Violations

FACILITY NAME (1)	GODFREY LAND MINE	NPDES	FLR10R783
-------------------	-------------------	-------	-----------

No ICIS Measurements Information Found.

## Compliance Schedules and Violations

FACILITY NAME (1)	GODFREY LAND MINE	NPDES	FLR10R783
-------------------	-------------------	-------	-----------

No Compliance Schedules Found.

## Pretreatment Inspections/Audits

FACILITY NAME (1)	GODFREY LAND MINE	NPDES	FLR10R783
-------------------	-------------------	-------	-----------

No ICIS Pretreatment Inspections Found.

## Pretreatment Performance Summary

FACILITY NAME (1)	GODFREY LAND MINE	NPDES	FLR10R783
-------------------	-------------------	-------	-----------

No ICIS Pretreatment Performance Summary Information Found.

Note: You are viewing results from the modernized data system, Integrated Compliance Information System (ICIS). The state reporting this data to EPA previously reported the data to a historic data system, Permit Compliance System (PCS). Use the following button to view the historic data from PCS.

