

...

General Offices . Selden Street, Berlin, Connecticut

P.O. BOX 270 HARTFORD, CONNECTICUT 06141-0270 (203) 665-5000

October 18, 1989

Docket No. 50-423

Re: 10CFR50.55a(g)

U.S. Nuclear Regulatory Commission Attention: Document Control Desk Washington, DC 20555

Gentlemen:

Millstone Nuclear Power Station, Unit No. 3 In-Service Inspection Summary Report

In accordance with 10CFR50.55a(g) and ASME Code Section XI, IWA-6230, "Summary Report Submittals," Northeast Nuclear Energy Company (NNECO) is providing to the NRC Staff the Millstone Nuclear Power Station, Unit No. 3, In-Service Inspection Summary Report. Attached to this letter is a copy of the In-Service Inspection Summary Report for the Millstone Unit No. 3 1989 Refueling Outage.

We hope you find this information satisfactory, and we remain available to answer any questions you may have.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

Senior Vace President

cc: W. T. Russell, Region I Administrator

D. H. Jaffe, NRC Project Manager, Millstone Unit No. 3

W. J. Raymond, Senior Resident Inspector, Millstone Unit Nos. 1, 2, and 3

8910230019 891018 PDR ADOCK 05000423

AOAT