## SAFEGUARDS INFORMATION



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30323

## OCT 03 1985

Report Nos. 50-335/85-24 and 50-389/85-24

Licensee: Florida Power and Light Company

9250 West Flagler Street

Miami, FL 33102

Docket Nos. 50-335 and 50-389

License Nos. DPR-67 and NPF-16

Facility Name: St. Lucie

Inspection Date: September 16 - 20, 1985

Inspector:

Jerry D. Ennis, Physical Security Inspector

Date Signed

Approved by:

D. R. McGuire, Chief, Physical Security Section Nuclear Materials Safety and Safeguards Branch Division of Radiation Safety and Safeguards

## SUMMARY

Scope: This routine, unannounced, physical security inspection entailed 34 inspector-hours onsite (three hours on backshift) inspecting: Management Effectiveness - Security Program; Security Organization; Security Program Audit; Testing and Maintenance; Locks, Keys, and Combinations; Lighting; Compensatory Measures; Access Control - Personnel, Packages, and Vehicles; Alarm Stations; Personnel Training and Qualification; and Safeguards Contingency Plan Implementation.

Results: No violations of regulatory requirements were identified

8510080288 851003 PDR ADOCK 05000335 PDR

SAFEGUARDS INFORMATION ENCLOSURE CONTAINS

ENCLOSURE CONTAINS SAPEGUARDS INFORMATION UPON SEPARATION THIS PAGE IS DECONTROLLED.